

### DAMAGE REPORT

Inbound carrier: AS NINA

ASNI403S 403S


19-Jan-2024 06:21

| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MSKU1735633 | BENT        | LEFT            |
| MRKU4440866 | BENT        | RIGHT           |
| MSKU4810638 | DENT        | LEFT            |
| SUDU7698037 | BROKEN      | BOTTOM          |
| TGHU1872495 | BENT        | RIGHT           |
| MRKU4773888 | BENT        | LEFT            |
| MNBU3410430 | HOLE        | TOPROOF         |
| MSKU9341955 | BENT        | RIGHT           |
| MSKU9341955 | BENT        | LEFT            |
| MNBU0072220 | CUT         | LEFT            |
| SUDU9301072 | BENT        | LEFT            |
| MNBU4075655 | BENT        | LEFT            |
| MNBU4075655 | BENT        | RIGHT           |
| MNBU0061458 | BENT        | LEFT            |
| MNBU0061458 | BENT        | RIGHT           |
| SUDU6075053 | BENT        | LEFT            |
| SUDU6075053 | BENT        | RIGHT           |
| MNBU0480428 | BENT        | RIGHT           |
| SUDU6055463 | BENT        | RIGHT           |
| SUDU8084408 | BENT        | RIGHT           |
| MSKU4274284 | IMO LABEL   | FRONT           |
| MRSU5241898 | IMO LABEL   | RIGHT           |
| MRSU5241898 | IMO LABEL   | LEFT            |
| MRSU5241898 | IMO LABEL   | BACK            |
| TRHU4380037 | BENT        | LEFT            |
| TRHU4380037 | BENT        | RIGHT           |
| SUDU8555848 | BENT        | LEFT            |
| TJNU9595253 | BENT        | RIGHT           |

MIV "AS NINA"  
IMO  
9401178  
Signed for receipt only,  
without prejudice of liability.  
Discharged same condition as  
loaded.

TJNU9595253  
Without any liability accepted  
Constanta South Container Terminal  
Planning Department

| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| SUDU6957093 | BENT        | RIGHT           |
| SUDU6957093 | BENT        | RIGHT           |
| TRHU8485587 | CUT         | TOPROOF         |
| TRLU7620633 | BENT        | LEFT            |
| MRKU5110107 | BENT        | RIGHT           |
| TRHU4577915 | CUT         | TOPROOF         |
| MSKU1132120 | BENT        | LEFT            |
| TCLU3362763 | CUT         | FRONT           |
| TCLU3362763 | BENT        | BOTTOM          |
| MRSU6209859 | DENT        | LEFT            |
| SUDU6069209 | BENT        | LEFT            |
| MNBU3980469 | SCRATCHED   | ENGINE          |
| MSKU0618632 | BENT        | RIGHT           |
| MSKU0618632 | BENT        | LEFT            |
| MRKU4654446 | IMO LABEL   | RIGHT           |
| MRKU4654446 | IMO LABEL   | RIGHT           |
| MSKU9785610 | BENT        | LEFT            |
| MSKU9528951 | BENT        | LEFT            |
| CRSU9325390 | BENT        | RIGHT           |
| MRKU6255825 | BENT        | RIGHT           |
| MRKU6255825 | BENT        | LEFT            |
| MRKU3342211 | IMO LABEL   | LEFT            |
| MRKU3342211 | IMO LABEL   | RIGHT           |
| MRKU7129204 | DENT        | CORNER          |
| PONU0394656 | BENT        | LEFT            |
| PONU0394656 | BENT        | RIGHT           |
| MRKU5548599 | BENT        | RIGHT           |
| MRKU5548599 | BENT        | LEFT            |
| MRKU3304042 | BENT        | LEFT            |
| MWCU5330741 | BENT        | RIGHT           |
| MNBU0154057 | BENT        | LEFT            |
| MNBU0154057 | BENT        | RIGHT           |
| SUDU6132045 | BENT        | FRONT           |
| MNBU3278278 | BENT        | RIGHT           |



Without any liability accepted  
Constantia South Container Terminal  
Planning Department

| Container   | Damage type | Damage location |
|-------------|-------------|-----------------|
| MNBU3440727 | BENT        | LEFT            |
| MNBU3440727 | BENT        | RIGHT           |
| MNBU4150569 | BENT        | RIGHT           |
| MNBU0066357 | BENT        | LEFT            |
| MNBU3292743 | BENT        | RIGHT           |
| MNBU3292743 | BENT        | TOPROOF         |
| MNBU0491401 | BENT        | RIGHT           |
| MSKU1827468 | DENT        | FRONT           |
| MNBU0457496 | BENT        | RIGHT           |
| MRKU3320700 | BENT        | LEFT            |
| MRKU5926981 | BENT        | RIGHT           |
| MRKU5926981 | DENT        | LEFT            |
| MRKU5926981 | BENT        | LEFT            |
| MRKU2822330 | BENT        | LEFT            |
| MSKU1768642 | BENT        | RIGHT           |
| MSKU1768642 | BENT        | LEFT            |
| SUDU8888089 | DENT        | RIGHT           |
| MSKU1642150 | DENT        | LEFT            |

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt only  
 without prejudice of liability.  
 Discharged same condition as  
 loaded.

AS NINA  
 IMO  
 9401178