

DAMAGE REPORT

Inbound carrier: AS NINA
ASNI413S 413S 09-Apr-2024 15:49

Container	Damage type	Damage location
MRSU3057393	HOLE	FRONT
MSKU9881681	BULGED	RIGHT
SUDU6510443	DENT	RIGHT
MSKU1513702	DENT	LEFT
MRKU3275962	BENT	BACK
MSKU4623299	DENT	BACK
MAEU4144981	CUT	TARPAULIN
MSKU4612334	DENT	LEFT
MNBU0626507	HOLE	TOPROOF
MAEU9161493	DENT	LEFT
MRKU4042688	DENT	RIGHT
PONU8104964	BENT	RIGHT
MRKU2805456	DENT	RIGHT
SUDU8759420	DENT	CORNERPOST
MSKU1179405	BENT	TOPROOF
MRSU3483104	DENT	RIGHT
TCNU1708788	BENT	LEFT
MSKU8835275	BENT	LEFT
MRKU3999660	BENT	LEFT
MRKU4223222	BENT	RIGHT
MSKU9477812	BENT	LEFT
CAIU6279609	BENT	LEFT
TCNU2821593	DENT	RIGHT
PONU8072363	BULGED	LEFT
TCNU4537631	TORN	DOORSYSTEM
SUDU4873769	CUT	TARPAULIN
SJKU2416860	CUT	TARPAULIN
MSKU5153292	BENT	RIGHT

*Signed for receipt only
without prejudice of liability
Discharged same condition as
loaded.*

IMO 9401178

M/V "AS NINA"

Without any liability accepted
Constanta South Container Terminal
Page 1 of 5
Planning Department

Container	Damage type	Damage location
MRSU3603431	DENT	LEFT
TRHU4757270	BENT	LEFT
SJKU2416509	RIPPED	TARPAULIN
MRKU9623860	BENT	RIGHT
CAIU6173704	BENT	LEFT
SUDU6840229	BENT	LEFT
FFAU5421793	DENT	LEFT
FFAU5408981	BENT	LEFT
MSKU8430003	BENT	RIGHT
MRKU7484976	BENT	FRONT
MRKU7484976	BENT	RIGHT
MRKU7484976	BENT	LEFT
MRSU5948690	BENT	RIGHT
MRSU5948690	BENT	LEFT
MRSU5276430	BENT	LEFT
PONU8071578	BENT	LEFT
GESU3445099	BENT	DOORSYSTEM
SJKU2416896	CUT	TARPAULIN
SJKU2416556	CUT	TARPAULIN
SJKU2415971	CUT	TARPAULIN
CAXU5789024	CUT	TARPAULIN
TEMU9758980	DENT	RIGHT
MNBU4001138	DIRTY	RIGHT
MAEU4136287	CUT	TARPAULIN
MRKU9539532	BENT	LEFT
FFAU5374650	BENT	RIGHT
MRKU2771994	BULGED	LEFT
MAEU4157211	CUT	TARPAULIN
SUDU8035173	DENT	LEFT
SUDU9014236	DENT	LEFT
MRSU6392348	BENT	LEFT
MRKU3599679	DENT	LEFT
MRKU7028195	BENT	RIGHT
MVIU0012563	DENT	LEFT

Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.

IMO
9401178

MV "AS NINA"

Without any liability accepted

Page 2 of 5

South Container Terminal
Planning Department


Container	Damage type	Damage location
MVIU0012563	DENT	RIGHT
MRKU2608170	DENT	RIGHT
MRKU2608170	DENT	LEFT
SUDU6709604	BENT	RIGHT
SUDU6291197	DENT	RIGHT
MRSU4393875	DENT	LEFT
CAIU8172590	DENT	LEFT
SUDU6971928	DENT	RIGHT
CAXU5784249	CUT	TARPAULIN
MRSU0220233	BENT	DOORSYSTEM
TEMU7424074	BENT	RIGHT
TEMU7424074	DENT	RIGHT
MRSU0058288	BENT	RIGHT
MRSU0058288	BENT	LEFT
MSKU0601244	BENT	CORNERPOST
PRSU0001789	CUT	TARPAULIN
CIPU5224211	BENT	LEFT
SUDU6075238	DENT	LEFT
MRKU0299575	DENT	LEFT
TLLU5983710	DENT	LEFT
MSKU8567995	DENT	LEFT
PONU7965000	DENT	RIGHT
MRKU7251110	DENT	RIGHT
SUDU5515034	DENT	LEFT
MAEU4235525	CUT	TARPAULIN
MRKU9826050	BENT	LEFT
TCNU7754292	DENT	RIGHT
TCNU7754292	DENT	LEFT
HASU4399940	BENT	LEFT
SUDU1936122	BENT	LEFT
TCLU3407282	BENT	RIGHT
TCLU3407282	BENT	LEFT
SUDU5169287	DENT	LEFT
MRKU2407895	BENT	RIGHT

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*



Without any liability accepted
Constanza South Container Terminal
Planning Department
Page 3 of 5

Container	Damage type	Damage location
MSKU5081660	BENT	RIGHT
TEMU7620605	BENT	LEFT
MRKU7936989	DENT	RIGHT
MSKU3411090	BENT	RIGHT
TCNU1725492	DIRTY	RIGHT
MIEU3028073	BENT	RIGHT
MIEU3028073	DENT	RIGHT
MRKU9455853	BENT	RIGHT
MRKU9455853	BENT	DOORSYSTEM
MRKU9455853	BENT	LEFT
TGHU1410964	DENT	RIGHT
MSKU1335128	BENT	LEFT
MAEU4230539	CUT	TARPAULIN
MAEU4110214	CUT	TARPAULIN
MSKU9999530	DENT	RIGHT
MSKU9999530	DENT	LEFT
MSKU9999530	BENT	LEFT
MSKU8795059	BENT	LEFT
MAGU5308285	BENT	RIGHT
MAGU5308285	DENT	LEFT
MMAU1278475	CUT	CABLE
MSKU3238106	DENT	RIGHT
MRKU3776774	DENT	LEFT
MRKU2664933	BENT	RIGHT
MRSU0017735	BENT	FRONT
MSKU7560872	HOLE	RIGHT
MRKU6824460	BENT	LEFT
MSKU8642487	BENT	LEFT
MSKU8642487	DENT	LEFT
MSKU8642487	BENT	RIGHT
SUDU6173580	BENT	LEFT
MAEU4085739	CUT	TARPAULIN
MAEU4048170	CUT	TARPAULIN
MSKU8612754	BENT	RIGHT



 Signed for receipt only,
 without prejudice of liability.
 Discharged same condition as
 loaded.

Without any liability accepted
 Constanta South Container Terminal
 Planning Department
 Page 4 of 5

Container	Damage type	Damage location
MSKU8612754	HOLE	RIGHT
MSKU8612754	BENT	LEFT
MSKU8612754	DENT	FLOOR
SUDU5608712	DENT	LEFT
BEAU6362344	BENT	LEFT
MRKU6638995	BENT	RIGHT
MNBU3192148	DENT	RIGHT
SUDU8545500	DENT	RIGHT
TRHU5235898	DENT	LEFT
MAEU4208052	CUT	TARPAULIN
MAEU4208052	BENT	RIGHT
IALU7225166	CUT	TARPAULIN
MSKU7551422	DENT	LEFT
MRKU4242541	DENT	LEFT
MRKU5405793	BENT	FRONT
MNBU3984612	DENT	RIGHT
MAEU4181028	CRACK	TARPAULIN
MNBU3589135	DENT	LEFT
SUDU5127403	BENT	RIGHT
SUDU5127403	BENT	LEFT

Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.

IMO
9401178

MTV "AS NINA"

Without any liability accepted
Constanta South Container Terminal
Planning Department

Page 5 of 5