

DAMAGE REPORT

Inbound carrier: MAERSK NEWPORT
MNEW418S 418S 09-May-2024 21:31

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCKU7322967 | DENT | LEFT |
| MRKU2273693 | DENT | LEFT |
| GCXU5791139 | DENT | FRONT |
| GCXU5791139 | DENT | LEFT |
| MNBU9123376 | DENT | RIGHT |
| MSKU8805080 | DENT | RIGHT |
| MSKU8805080 | DENT | LEFT |
| MSKU1216957 | BENT | RIGHT |
| TCNU2813812 | BENT | LEFT |
| MSKU5122291 | DENT | RIGHT |
| MSKU5122291 | DENT | LEFT |
| MRKU6743650 | DENT | CORNERPOST |
| MRKU6743650 | DENT | LEFT |
| MRKU3201194 | DENT | RIGHT |
| MRKU3201194 | DENT | LEFT |
| TGBU6675199 | DENT | RIGHT |
| TGBU6675199 | DENT | LEFT |
| HASU4185634 | IMO LABEL | FRONT |
| IPXU3998572 | BENT | BOTTOM |
| IPXU3998572 | DENT | LEFT |
| MRKU8122673 | DENT | LEFT |
| MSKU7716184 | BENT | LEFT |
| MSKU1686035 | BENT | RIGHT |
| MSKU1686035 | BENT | LEFT |
| MSKU1571592 | BENT | RIGHT |
| MSKU1571592 | DENT | LEFT |
| MRKU4446587 | DENT | LEFT |
| SUDU6510649 | DENT | LEFT |

ob

Receipt only

Without any liability assumed
 Constanta South Container Terminal
 Planning Department
 Page 1 of 7

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| SUDU6510649 | DENT | RIGHT |
| HASU4843078 | BENT | LEFT |
| PONU8222036 | DENT | LEFT |
| MRSU5374083 | DENT | RIGHT |
| MRSU5374083 | BENT | LEFT |
| MRSU5374083 | DENT | LEFT |
| MSKU0478588 | BENT | RIGHT |
| MSKU0478588 | DENT | LEFT |
| MRKU4623044 | DENT | RIGHT |
| MRKU4623044 | DENT | LEFT |
| MRKU4623044 | DENT | CORNERPOST |
| MRKU5578572 | DENT | CORNERPOST |
| MSKU9283524 | BENT | RIGHT |
| MSKU9283524 | DENT | LEFT |
| MSKU9283524 | DENT | CORNERPOST |
| TCNU4381894 | DIRTY | RIGHT |
| TCNU4381894 | DENT | RIGHT |
| TCNU4381894 | DENT | LEFT |
| MRSU4525436 | DENT | CORNERPOST |
| MRSU4525436 | DENT | LEFT |
| MNBU3016112 | HOLE | FRONT |
| MNBU3016112 | DENT | FRONT |
| TRHU8414428 | BENT | RIGHT |
| GESU6001246 | DENT | LEFT |
| MSKU4172960 | DENT | FRONT |
| MSKU8529737 | DENT | RIGHT |
| MSKU8529737 | RUSTED | RIGHT |
| MSKU8529737 | DENT | LEFT |
| MWCU5322664 | DENT | LEFT |
| MSKU1408137 | DENT | RIGHT |
| MSKU1408137 | BENT | LEFT |
| MSKU9224624 | RUSTED | FRONT |
| MSKU9224624 | BENT | RIGHT |
| MSKU9224624 | DENT | CORNERPOST |

do *[Signature]*

MAERSK A/S
 9356127
 MAERSK IFWPORT

[Handwritten signature]

Without any liability accepted
 Constanta South Container Terminal
 Planning Department


Page 2 of 7

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| MSKU0258156 | BENT | LEFT |
| MRKU2588469 | DENT | LEFT |
| SEKU4720152 | DENT | LEFT |
| TRLU6901111 | BENT | RIGHT |
| TRLU6901111 | BENT | LEFT |
| TRLU6901111 | DENT | LEFT |
| MRSU5383212 | DENT | CORNERPOST |
| MRSU3898570 | DENT | CORNERPOST |
| MRKU4508420 | BENT | RIGHT |
| MRKU4508420 | DENT | LEFT |
| MWCU5318303 | DENT | LEFT |
| MRKU5921948 | DENT | LEFT |
| MIEU3076940 | DENT | LEFT |
| HASU4590750 | DENT | RIGHT |
| HASU4590750 | DENT | CORNERPOST |
| UETU5697836 | BENT | RIGHT |
| UETU5697836 | DENT | LEFT |
| TRLU8053827 | DENT | LEFT |
| MRSU3793394 | HOLE | TOPROOF |
| MNBU0216056 | DENT | RIGHT |
| MNBU0216056 | DENT | LEFT |
| MNBU3429796 | DENT | LEFT |
| MMAU1169366 | DENT | RIGHT |
| MMAU1169366 | DENT | LEFT |
| MWCU5293648 | DENT | RIGHT |
| MWCU5293648 | DENT | LEFT |
| MRKU8365842 | BENT | RIGHT |
| MRKU8365842 | BENT | BOTTOM |
| MSWU1013190 | DENT | RIGHT |
| MSWU1013190 | DENT | LEFT |
| MRKU3047514 | DENT | LEFT |
| MRKU3047514 | DENT | RIGHT |
| SUDU8203092 | DENT | LEFT |
| TCNU2737939 | BENT | FRONT |



Without any liability accepted
 Page 8 of 7
 Constanta South Container Terminal
 Planning Department

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCNU2737939 | BENT | RIGHT |
| TCNU2737939 | DENT | RIGHT |
| MRKU4517680 | BENT | RIGHT |
| MRKU4517680 | BENT | LEFT |
| MSKU7572071 | DENT | LEFT |
| MSKU7837252 | DENT | LEFT |
| TCLU3022418 | DENT | RIGHT |
| TCLU3022418 | BENT | BOTTOM |
| MSKU1788063 | DIRTY | RIGHT |
| MSKU1788063 | BENT | LEFT |
| SUDU8939268 | BENT | RIGHT |
| SUDU8939268 | DENT | LEFT |
| MSKU0009180 | BENT | RIGHT |
| MSKU0009180 | RUSTED | FRONT |
| MSKU0009180 | BENT | LEFT |
| MRKU5632009 | BENT | RIGHT |
| MRKU5632009 | BENT | LEFT |
| MIEU2004971 | BENT | RIGHT |
| MSKU8909573 | BENT | RIGHT |
| MSKU8909573 | DENT | LEFT |
| CXDU1919410 | DENT | RIGHT |
| MRSU6563395 | DENT | LEFT |
| SUDU6006875 | DENT | LEFT |
| MRKU3542375 | DENT | RIGHT |
| MRKU3542375 | BENT | RIGHT |
| MRKU3542375 | DENT | CORNERPOST |
| TCLU5153947 | HOLE | TOPROOF |
| MSKU4264481 | DENT | RIGHT |
| MSKU4264481 | BENT | LEFT |
| SUDU7735681 | BENT | RIGHT |
| SUDU7735681 | DENT | LEFT |
| MRKU7806326 | DENT | LEFT |
| MSKU2965327 | BENT | BOTTOM |
| HASU1564790 | DENT | LEFT |



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRKU8772370 | BENT | BOTTOM |
| MRKU8772370 | DENT | LEFT |
| MNBU9113228 | DENT | RIGHT |
| MNBU3306533 | DENT | LEFT |
| MNBU4174874 | DENT | TOPROOF |
| MNBU3470676 | DENT | CORNERPOST |
| MRSU3731052 | DENT | CORNERPOST |
| TLLU5826748 | DENT | RIGHT |
| MRKU3721581 | BENT | LEFT |
| TCKU1745154 | BENT | LEFT |
| MNBU3151370 | DENT | RIGHT |
| MNBU3151370 | DENT | LEFT |
| MNBU3481557 | DENT | LEFT |
| TCLU2477156 | BENT | BOTTOM |
| MSKU9753891 | BENT | LEFT |
| MNBU0292539 | DENT | FRONT |
| TCKU7985189 | BENT | LEFT |
| MSKU5786475 | DENT | LEFT |
| MSKU5786475 | BENT | RIGHT |
| MSKU5786475 | BENT | BOTTOM |
| MRKU9573624 | BENT | RIGHT |
| PONU8131960 | DENT | LEFT |
| PONU8131960 | DENT | RIGHT |
| MRKU9453784 | BENT | LEFT |
| CAAU5292033 | BENT | LEFT |
| HASU4345413 | DENT | RIGHT |
| MRSU3123617 | DENT | RIGHT |
| MRSU3123617 | BENT | LEFT |
| MRSU4659097 | DENT | LEFT |
| MSKU0558549 | BENT | RIGHT |
| HASU5069562 | BENT | RIGHT |
| MRKU5094562 | DENT | RIGHT |
| HASU4052380 | DENT | RIGHT |
| HASU4052380 | BENT | RIGHT |



Without any liability accepted
 Constanta South Container Terminal
 Planning Department
 Page 5 of 7

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRKU2348616 | BENT | RIGHT |
| MRKU2348616 | DENT | LEFT |
| MRKU5784871 | DENT | LEFT |
| MRKU5784871 | DENT | CORNERPOST |
| FFAU5224069 | BENT | RIGHT |
| FFAU5224069 | BENT | LEFT |
| SUDU8663164 | DENT | LEFT |
| PONU7986657 | DENT | CORNERPOST |
| PONU7986657 | BENT | RIGHT |
| PONU7986657 | BENT | LEFT |
| MRSU3485175 | RUSTED | FRONT |
| MRKU2416140 | DENT | RIGHT |
| MRKU2416140 | DENT | LEFT |
| MSKU7453149 | DENT | LEFT |
| TCLU3236636 | DENT | FRONT |
| MSKU5946830 | BENT | LEFT |
| MSKU5946830 | DENT | RIGHT |
| SEKU4628180 | DENT | RIGHT |
| TCKU7991941 | BENT | FRONT |
| TCKU7991941 | DENT | RIGHT |
| TCKU3598582 | BENT | LEFT |
| MSKU5958255 | BENT | BOTTOM |
| MSKU5958255 | BENT | RIGHT |
| MSKU5958255 | DENT | LEFT |
| MRKU7604367 | BENT | RIGHT |
| MRKU7604367 | DENT | LEFT |
| MRKU7604367 | BENT | LEFT |
| HASU1149850 | DENT | RIGHT |
| HASU1149850 | BENT | LEFT |
| MSKU5636731 | DENT | RIGHT |
| MRKU6704799 | BENT | BOTTOM |
| TEMU4465104 | DENT | LEFT |
| PONU0062055 | BENT | BOTTOM |
| MIEU3060780 | DENT | LEFT |

clo
Receipt only


Without any liability accepted
 Page 6 of 7
 Constanta South Container Terminal
 Planning Department

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCLU8532800 | DENT | CORNERPOST |
| TCLU8532800 | BENT | LEFT |
| TCLU8532800 | DENT | LEFT |
| TCNU6227960 | DENT | LEFT |
| TCNU4377132 | BENT | RIGHT |
| TCNU4377132 | BENT | LEFT |
| MRKU3406337 | DENT | RIGHT |
| TGBU9307550 | BENT | RIGHT |
| TGBU9307550 | DENT | LEFT |
| MRKU2911951 | DENT | RIGHT |
| MRKU2911951 | DENT | CORNERPOST |
| MRSU3800702 | CUT | FRONT |
| MRSU3800702 | HOLE | FRONT |
| MRKU0697861 | DENT | LEFT |
| MRKU2619472 | BENT | RIGHT |
| MRKU2619472 | BENT | LEFT |
| TCNU5627112 | DENT | LEFT |
| MSKU8554508 | DENT | RIGHT |
| MSKU8554508 | DENT | LEFT |

Handwritten signature
Next
MAERSK A/S
9356127
MAERSK IFWPORT

Without any liability accepted
page 7 of 7
Constanta South Container Terminal
Planning Department