

DAMAGE REPORT

Inbound carrier: MAERSK NEWPORT
MNEW421S 421S 22-May-2024 09:38

Container	Damage type	Damage location
TLLU7663104	BENT	LEFT
MRKU3446010	DENT	LEFT
UESU4568358	DENT	CORNERPOST
MRKU3485948	BENT	LEFT
GCXU5758300	DENT	RIGHT
GCXU5758300	DENT	BOTTOM
MRKU5515168	DENT	RIGHT
MRSU4636574	DENT	LEFT
TCKU7739170	DENT	CORNER
TGHU6797630	DENT	RIGHT
MRKU7902905	CUT	BACK
MRKU7902905	DENT	DOORSYSTEM
CAAU5267386	DENT	RIGHT
TLLU5368218	BENT	FRONT
MRSU3545340	CUT	TARPAULIN
MRSU3545340	HOLE	TARPAULIN
SUDU8225580	DENT	RIGHT
MSKU6760789	DENT	FLOOR
MSKU6760789	BENT	LEFT
MNBU0670618	DENT	RIGHT
MSKU0397341	DENT	LEFT
MSKU1641771	DENT	LEFT
TCLU5342508	BENT	RIGHT
TCLU5342508	BENT	LEFT
MRKU6274846	DENT	RIGHT
MRKU3759859	DENT	LEFT
TCLU6511428	BENT	RIGHT
CAAU6640318	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

3/2
MAERSK NEWPORT
DISCHARGED AS LOADED

Container	Damage type	Damage location
MSKU9495246	BENT	RIGHT
MSKU9495246	BENT	LEFT
MSKU0431050	BENT	LEFT
MSKU0431050	DENT	LEFT
MSKU9234725	DENT	LEFT
TGBU6645506	DENT	RIGHT
MSKU9723578	DENT	CORNERPOST
MRSU4152991	BENT	RIGHT
MRSU4152991	BENT	LEFT
CAXU9273566	DENT	RIGHT
MRKU4269368	BENT	RIGHT
MRSU3257318	BENT	LEFT
MRSU3257318	BENT	RIGHT
MRKU6244800	BENT	LEFT
MRKU2223389	DENT	RIGHT
MRKU2223389	BENT	RIGHT
MRSU3741282	DENT	LEFT
MRKU4689118	DENT	LEFT
SUDU1488049	DENT	FRONT
MRSU6068046	DENT	LEFT
MRSU6068046	DENT	RIGHT
TCNU2475187	DENT	LEFT
MRKU3315767	DENT	RIGHT
HASU4851685	DENT	LEFT
MNBU3108585	CUT	RIGHT
MSKU7267972	BENT	RIGHT
TRHU2170828	DENT	RIGHT
MSKU3919115	DENT	LEFT
MSKU4286243	BROKEN	CORNERPOST
MRSU0548520	HOLE	TOPROOF
MRKU8777768	DENT	LEFT
XINU1260791	HOLE	BOTTOM
MSKU9143775	HOLE	TARPAULIN
MRKU5379040	BENT	RIGHT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Page 2 of 4
 31.05.24
 MAERSK NEWPORT
 DISCHARGED AT WORKED

Container	Damage type	Damage location
MRKU5379040	DENT	RIGHT
SUDU8987646	BENT	RIGHT
SUDU8987646	DENT	RIGHT
MRKU4775108	BENT	RIGHT
SUDU7681585	DENT	RIGHT
TCLU3236071	DENT	RIGHT
TCLU3236071	HOLE	FRONT
MRKU5676012	DENT	LEFT
TCNU7873075	DENT	LEFT
PONU8235096	DENT	LEFT
BEAU6373550	BENT	LEFT
MRKU5779176	DENT	LEFT
TLLU5826054	BENT	LEFT
TLLU5826054	DENT	FRONT
MSKU7651870	HOLE	BOTTOM
TCNU8793077	DENT	RIGHT
CAAU6479420	BENT	RIGHT
CAAU6479420	DENT	RIGHT
CAAU6479420	BENT	LEFT
CAAU6479420	DENT	LEFT
TRHU5257182	BENT	RIGHT
TRHU5257182	DENT	RIGHT
PONU7899207	BENT	LEFT
PONU7899207	DENT	LEFT
MRKU2977455	DENT	RIGHT
MSKU1345023	DENT	LEFT
MSKU1345023	DENT	RIGHT
TRHU6216486	DENT	LEFT
MRKU5134900	DENT	RIGHT
MNBU9065536	HOLE	TOPROOF
MRSU4323559	BENT	LEFT
MRKU2005406	BENT	LEFT
MRKU0928087	DENT	FLOOR
MRKU0928087	BENT	LEFT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Page 8 of 4
 MAERSK NEWPORT
 DISCHARGED AS LATER

Container	Damage type	Damage location
MRKU2014310	DENT	RIGHT
MSKU6509731	DENT	FLOOR
MSKU6509731	BENT	LEFT
GCXU5658086	BENT	LEFT
TCKU7329473	DENT	LEFT
MRKU3107043	BENT	RIGHT
MRKU3309321	DENT	LEFT
MRSU4936268	HOLE	TARPAULIN
MRSU3310599	BENT	LEFT
MSKU3942687	BENT	RIGHT
MRKU4884201	BENT	LEFT
MRKU4418292	BENT	LEFT
TCKU7706242	DENT	RIGHT
TCKU7706242	DENT	LEFT
MSKU1366197	DENT	LEFT
MSKU1248553	DENT	LEFT
MRSU5203394	DENT	LEFT
MRSU5203394	SCRATCHED	LEFT
MSKU9970270	DENT	CORNERPOST
MRKU9214624	BENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

3/0
Page 4 of 4
MAERSK NEWPORT
DISCHARGED AS
LOADED