

DAMAGE REPORT

Inbound carrier: AS NINA

ASNI344S 344S

10-Nov-2023 04:18

Container	Damage type	Damage location
MSKU0254320	BENT	LEFT
MRSU4842174	DENT	FRONT
MRSU4842174	DENT	LEFT
MRKU4832023	IMO LABEL	FRONT
SUDU8227197	BENT	RIGHT
TCKU1351124	BENT	LEFT
TCKU1069764	BENT	RIGHT
TCKU1069764	BENT	LEFT
MRKU9041581	BENT	RIGHT
MRKU9041581	BENT	LEFT
MSKU4441951	BENT	RIGHT
MSKU4441951	BENT	LEFT
MSKU4282232	BENT	LEFT
MRKU2122110	DENT	LEFT
PONU0573543	DENT	LEFT
MSKU1131700	DENT	LEFT
MRKU3724071	BENT	FRONT
MRKU3724071	DENT	RIGHT
TGBU5322221	BENT	LEFT
MRKU0063403	DENT	RIGHT
HASU1558400	BENT	LEFT
PONU1824685	BENT	RIGHT
PONU1824685	DENT	LEFT
SUDU6631569	DENT	LEFT
MSKU7095873	BENT	LEFT
MSKU3283701	BENT	LEFT
DFSU6732580	BENT	FRONT
DFSU6732580	BENT	LEFT

Signed for receipt only, without prejudice of liability. Discharged same condition as loaded.

IMO 9401178

AS NINA

Without any liability accepted
Constanta South Container Terminal
Page 1 of 6



Container	Damage type	Damage location
TCNU9875631	BENT	LEFT
MSKU2794461	BENT	LEFT
MSKU2794461	BENT	RIGHT
MRKU9650660	CUT	RIGHT
MRKU9650660	HOLE	RIGHT
MRKU9650660	DENT	LEFT
MRKU8365333	BENT	LEFT
MRKU5488490	BENT	FRONT
MRKU9212792	DENT	CORNER
MRKU9212792	BROKEN	CORNER
MRKU8211235	HOLE	FRONT
SUDU1406781	DENT	FRONT
MAEU4690853	HOLE	TARPAULIN
TEMU2262026	BENT	LEFT
MSKU3956607	BENT	FRONT
MSKU3956607	BENT	RIGHT
MSKU3956607	BENT	LEFT
TRHU2192895	BENT	RIGHT
TRHU2192895	DENT	LEFT
MRKU8739773	BENT	LEFT
MRKU7457369	BENT	RIGHT
MRKU7457369	BENT	LEFT
MSKU4135606	BENT	RIGHT
MSKU4135606	BENT	LEFT
TCNU9866223	BENT	FRONT
MSKU5434068	BENT	RIGHT
MRKU6773022	BENT	LEFT
MAEU4724418	HOLE	TARPAULIN
TCKU2533545	DENT	LEFT
MSKU5644721	DENT	LEFT
MSKU4334613	BENT	RIGHT
MSKU4334613	BENT	LEFT
MSKU3102953	DENT	RIGHT
TCLU1758518	BENT	LEFT





Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.

Without any liability accepted
Constante S.A. Container Terminal
Planning Department


Container	Damage type	Damage location
MSKU6980654	BENT	RIGHT
MRKU4292795	BENT	FRONT
MRKU4292795	DENT	LEFT
MRKU4292795	BENT	LEFT
MSKU3344469	BENT	RIGHT
SUDU7494579	DENT	RIGHT
SUDU7494579	BENT	LEFT
MRKU7329814	BENT	FRONT
MRKU7329814	BENT	LEFT
MRKU9149508	BENT	LEFT
MSKU6924265	BENT	RIGHT
MSKU6924265	BENT	LEFT
MSKU6924265	DENT	FLOOR
MRKU3740431	BENT	RIGHT
TRLU8240073	HOLE	TOPROOF
MNBU0040990	BENT	LEFT
MNBU0040990	BENT	RIGHT
GLDU7529487	BENT	LEFT
PONU0008732	DENT	LEFT
HASU4925216	DENT	LEFT
MRKU3496747	DENT	LEFT
MRKU6108866	DENT	LEFT
MSKU9959917	BENT	RIGHT
CAAU5426277	BENT	LEFT
MNBU3017422	DENT	RIGHT
PONU7844483	DENT	LEFT
TCKU6171953	DENT	LEFT
MSKU8462248	BENT	RIGHT
MSKU8462248	DENT	LEFT
MSKU9727070	BENT	RIGHT
MRKU5622675	BENT	RIGHT
MRKU2530955	BENT	LEFT
HASU4490366	BENT	LEFT
INKU2224763	BENT	LEFT



Container	Damage type	Damage location
MNBU3575907	DENT	RIGHT
APMU2959672	BENT	LEFT
MSKU4387207	CUT	FRONT
BMOU4654995	CUT	DOOR
GESU3668533	DENT	RIGHT
TGBU6679980	BENT	FRONT
MSKU9582377	BENT	FRONT
MSKU9782272	DENT	RIGHT
PONU1844130	BENT	LEFT
PONU1844130	DENT	LEFT
MRKU0565063	BENT	RIGHT
MRKU0565063	BENT	LEFT
MRSU3947268	BENT	RIGHT
MRKU4711870	BENT	LEFT
MRKU4495508	DENT	LEFT
MRKU3056584	BENT	RIGHT
PONU7974168	BENT	RIGHT
PONU7974168	BENT	LEFT
MRKU0921138	DENT	LEFT
MRKU0634138	DENT	LEFT
MRKU2122824	BENT	LEFT
MRKU2122824	DENT	LEFT
MRKU2122824	BENT	RIGHT
SUDU6634824	BENT	LEFT
PONU7950227	BENT	RIGHT
PONU7950227	DENT	LEFT
MRKU5960538	BENT	RIGHT
TCLU5196105	BENT	FRONT
TCLU5196105	BENT	RIGHT
TCLU5196105	BENT	LEFT
MRKU3014634	BENT	RIGHT
MRKU3014634	BENT	LEFT
MRKU2787326	BENT	RIGHT
MRKU2787326	BENT	LEFT



Container	Damage type	Damage location
HASU4549572	DENT	RIGHT
HASU4549572	DENT	LEFT
MNBU0556204	BENT	RIGHT
UACU5074277	BENT	FRONT
UACU5074277	BENT	LEFT
MSKU7543181	BENT	BOTTOM
MRSU4185212	BENT	LEFT
MRKU8797960	BENT	RIGHT
MSKU8892589	DENT	LEFT
SUDU6870624	DENT	LEFT
MRKU3074130	DENT	LEFT
MSKU1765936	DENT	LEFT
MSKU4392820	BENT	BOTTOM
MRKU6708135	DENT	LEFT
MSKU3694810	BENT	FRONT
MSKU3694810	BENT	RIGHT
MRKU5511476	IMO LABEL	FRONT
MRKU2027112	BENT	RIGHT
MRKU2027112	DENT	RIGHT
MRKU2027112	BENT	LEFT
MRSU3233229	BENT	LEFT
MSKU9750423	BENT	RIGHT
TLLU5352090	DENT	LEFT
MRSU4787328	BENT	LEFT
GCXU5706287	DENT	LEFT
MRKU5818441	BENT	LEFT
MIEU0050324	BENT	DOOR
MIEU0050324	DENT	RIGHT
MIEU0050324	BENT	LEFT
PONU7909178	BENT	LEFT
MSKU0491867	BENT	RIGHT
MSKU0491867	BENT	LEFT
MSKU1211810	DENT	LEFT
MRKU7177840	BENT	RIGHT



Container	Damage type	Damage location
MRKU7177840	BENT	LEFT
MRKU5742557	DENT	LEFT
CAIU2719166	DENT	LEFT
MSKU9527873	BENT	RIGHT
MSKU9527873	DENT	LEFT
SUDU8516163	BENT	RIGHT
SUDU8516163	DENT	LEFT
MRSU6123992	DENT	LEFT
MRKU5258291	BENT	LEFT
MSKU6693079	DENT	RIGHT
CAAU5221765	DENT	RIGHT
MRKU2542257	BENT	RIGHT
MRKU2542257	DENT	LEFT
MRKU4253438	BENT	RIGHT
MRKU4253438	DENT	LEFT
MSKU0559191	BENT	LEFT

