

**DAMAGE REPORT**

Inbound carrier: AS NINA

ASNI346S 346S

24-Nov-2023 21:56

Container	Damage type	Damage location
MRSU3335724	BENT	RIGHT
MRSU3335724	BENT	LEFT
PONU7880860	DENT	LEFT
MWCU5332446	BENT	RIGHT
MWCU5332446	BENT	LEFT
MRKU9285130	BENT	LEFT
MRKU7698371	BENT	RIGHT
MRKU7368209	BENT	LEFT
MRKU7368209	BENT	RIGHT
MNBU0314746	SCRATCHED	RIGHT
MSKU5245742	BENT	DOORSYSTEM
MSKU5245742	BENT	LEFT
TCNU2439092	BENT	LEFT
TCNU2439092	BENT	BOTTOM
MVIU0029340	BENT	RIGHT
MRKU6136209	BENT	RIGHT
MRKU6136209	DENT	CORNERPOST
TCKU6039295	DENT	RIGHT
MRSU3286065	DENT	CORNERPOST
MRKU6162229	DENT	LEFT
MRSU3529397	DENT	CORNERPOST
MRSU3529397	BENT	RIGHT
MRKU8611397	BENT	BOTTOM
MRKU8611397	DENT	RIGHT
MRKU7754578	DENT	FRONT
MRKU7780052	DENT	RIGHT
TCNU4471386	DENT	LEFT
HASU4622225	DENT	RIGHT

Without liability accepted  
Constanta South Container Terminal  
Planning Department

AS NINA receipt only,  
without prejudice of liability.  
IMO 9401178  
Discharged same condition as loaded.

Container	Damage type	Damage location
MSKU9329630	DENT	RIGHT
TCLU9243062	BENT	LEFT
MAEU4143100	CUT	TARPAULIN
PONU1730138	BENT	LEFT
MRKU5528545	DENT	RIGHT
MRKU5528545	DENT	LEFT
TCLU2900530	DENT	RIGHT
TCLU2900530	DENT	LEFT
LLTU2054766	BENT	FLOOR
TCKU6971323	DENT	RIGHT
MRSU4151850	DENT	RIGHT
SUDU7309942	BENT	BOTTOM
MRKU6575623	DENT	LEFT
MSKU5997101	BENT	BOTTOM
TCKU7412567	BENT	LASHING
MRKU8433546	BENT	BOTTOM
MRKU8433546	BENT	RIGHT
MRKU8433546	DENT	RIGHT
MRSU0041177	BENT	BOTTOM
TGHU6180587	DENT	RIGHT
MRKU5494297	BENT	LEFT
MRKU5494297	BENT	RIGHT
BEAU5920570	IMO LABEL	DOOR
MSKU0734946	DENT	LEFT
MSKU0734946	BENT	LEFT
MRSU3604361	DENT	LEFT
SUDU1894011	BENT	BOTTOM
MSKU8990543	DENT	LEFT
TCNU8710920	DENT	RIGHT
MSKU0804703	DENT	LEFT
SUDU6873201	BENT	LEFT
MRSU4541191	DENT	LEFT
HASU4799859	DENT	FRONT
CAAU5488880	DENT	LEFT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt only,  
 without prejudice of liability  
 Discharged same condition as  
 loaded.



Container	Damage type	Damage location
MRKU9132254	BENT	LEFT
MRKU3711686	DENT	LEFT
CAAU6088641	DENT	LEFT
TRHU4380989	BENT	RIGHT
MAEU3427903	DENT	CORNERPOST
MAEU3427903	DENT	BOTTOM
TGBU6689377	DENT	RIGHT
TRLU9342275	BENT	LEFT
FCIU8975760	DENT	RIGHT
FCIU8975760	DENT	CORNERPOST
MMAU1062608	DENT	RIGHT
MMAU1062608	DENT	LEFT
MVIU0022140	BENT	CORNER
TCNU2481600	IMO LABEL	FRONT
MRKU3567100	BENT	RIGHT
MSKU4719852	DENT	LEFT
MSKU4231045	BENT	BOTTOM
MSKU4231045	DENT	RIGHT
MSKU4231045	DENT	LEFT
SUDU8741734	DENT	LEFT
HASU4862170	DENT	LEFT
SUDU7767267	BENT	BOTTOM
HASU1084677	DENT	FRONT
HASU1084677	DENT	RIGHT
HASU1084677	DENT	LEFT
MRSU3324993	DENT	LEFT
MRKU6254270	DENT	RIGHT
MRKU6254270	DENT	LEFT
MRSU6457074	DENT	RIGHT
MRSU4912250	DENT	RIGHT
MRKU8822532	TORN	CORNER
MRKU8822532	BENT	CORNERPOST
MRKU8822532	BENT	LEFT
MRKU3107418	DENT	RIGHT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt only,  
 without prejudice of liability  
 Discharged same condition as  
 loaded.

AS NINA  
 IMO  
 9401178

Container	Damage type	Damage location
TRHU4806077	DENT	RIGHT
CIPU5059890	HOLE	TOPROOF
MWCU6811870	DENT	RIGHT
MWCU6811870	DENT	TOPROOF
MWCU6811870	DENT	LEFT
MRKU3601837	DENT	LEFT
MSKU3303855	BENT	LEFT
MSKU3303855	BENT	BOTTOM
SUDU8786472	BENT	RIGHT
MRKU2560646	BENT	LEFT
SUDU8564650	BENT	RIGHT
UETU2449224	BENT	RIGHT
BSIU8054037	BENT	LEFT
BSIU8054037	BENT	RIGHT
SUDU7663771	TORN	DOORSYSTEM
SUDU7663771	BENT	LEFT
TGHU1752530	BENT	BOTTOM
TGHU1752530	DENT	LEFT
MRKU7345332	BENT	BOTTOM
MRKU7345332	BENT	RIGHT
MRKU9572490	BENT	BOTTOM
SUDU7746310	BENT	BOTTOM
MSKU2629831	BENT	BOTTOM
MSKU2629831	BENT	RIGHT
MSKU5239210	BENT	BOTTOM
MRKU8282239	BENT	LEFT
GCXU5702996	CUT	FRONT
GCXU5702996	DENT	LEFT
MRKU4063947	DENT	RIGHT
MRKU5934673	DENT	LEFT
MRKU5934673	IMO LABEL	DOOR
PONU7899681	BENT	LEFT
PONU7899681	BENT	BOTTOM
MRKU4895865	DENT	LEFT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt only,  
 without prejudice of liability,  
 Discharged same condition as  
 loaded.

AS NINA  
 IMO  
 9401178



Container	Damage type	Damage location
MRKU2062427	BENT	LEFT
MIEU0034663	DENT	RIGHT
HASU1553558	TORN	DOORSYSTEM
HASU1553558	BENT	LEFT
HASU1553558	BENT	RIGHT
CAAU6400934	BENT	RIGHT
TCNU2817567	DENT	LEFT
TCNU2817567	DENT	RIGHT
PONU8063320	DENT	RIGHT
PONU8063320	BENT	RIGHT
CAIU4693380	IMO LABEL	FRONT
MSKU3620504	TORN	DOORSYSTEM
TGHU1764931	BENT	BOTTOM
TCLU1609200	DENT	LEFT
SUDU6584446	DENT	LEFT
TEMU5081649	BENT	BOTTOM
MSKU3401363	DENT	LEFT
TRHU4442735	DENT	LEFT
MSKU0704197	DENT	RIGHT
MRKU5349787	BENT	LEFT
SUDU8567427	DENT	RIGHT
MSKU1432730	DENT	LEFT
MNBU3095744	DENT	RIGHT
MNBU3095744	DENT	LEFT
TEMU7942828	DENT	FRONT
MWCU6984346	DENT	RIGHT
GCXU5725163	BENT	LEFT
CAIU8732925	DENT	RIGHT
CAIU8732925	BENT	LEFT
SUDU8672989	DENT	CORNERPOST
SUDU8672989	DENT	LEFT
SUDU8672989	DENT	RIGHT
MRKU3752659	DENT	RIGHT
MRKU3752659	BENT	LEFT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt of cargo  
 without prejudice of liability.  
 Discharged same condition as  
 loaded.

Page 5 of 8

IMO "AS NINA"  
 IMO  
 9401178

Container	Damage type	Damage location
MRKU3752659	DENT	LEFT
MRSU4585728	BENT	BOTTOM
MRSU4585728	DENT	LEFT
TEMU7545939	DENT	RIGHT
TEMU7545939	BENT	LEFT
MRKU4993141	DENT	LEFT
MRKU7529962	BENT	BOTTOM
MRKU9110580	BENT	BOTTOM
MRKU9110580	BENT	RIGHT
MSKU5474163	DENT	RIGHT
SUDU6108347	BENT	LEFT
MSKU5772759	BENT	LEFT
MSKU5772759	BENT	RIGHT
MSKU7010201	BENT	BOTTOM
SUDU6699738	BENT	LEFT
MRKU4666215	DENT	RIGHT
GCXU5546337	BENT	RIGHT
GCXU5546337	BENT	LEFT
PONU8096560	DENT	LEFT
MRKU1022327	DENT	LEFT
MRKU6742438	DENT	RIGHT
MRKU6785018	DENT	LEFT
TLLU2395570	BENT	RIGHT
MSKU5177165	BENT	BOTTOM
MRKU7049161	BENT	BOTTOM
MRKU7049161	DIRTY	RIGHT
HASU1234020	BENT	BOTTOM
MSKU7432125	DENT	RIGHT
SUDU2841778	CUT	TARPAULIN
MRSU5037652	DENT	LEFT
MRSU5037652	BENT	LEFT
MRSU3340253	BENT	LEFT
SUDU9004650	DENT	RIGHT
SUDU9004650	BENT	LEFT

Without any liability accepted  
 Constanta South Container Terminal  
 Planning Department

Signed for receipt on  
 without prejudice of liability.  
 Discharged same condition as  
 loaded.



Container	Damage type	Damage location
TCNU8683790	DENT	CORNERPOST
MNBU0431402	DENT	TOPROOF
MNBU0431402	DENT	RIGHT
MNBU0431402	DENT	CORNERPOST
SUDU8074858	DENT	RIGHT
SUDU8074858	DENT	LEFT
SUDU8074858	DENT	FRONT
MRKU3529115	DENT	RIGHT
MRKU3529115	DENT	LEFT
CAAU6450175	DENT	LEFT
MRKU0478610	DENT	LEFT
MRSU5439604	IMO LABEL	FRONT
TCKU7642214	DENT	RIGHT
MRKU1062295	DENT	LEFT
MRKU8569790	DENT	RIGHT
MRKU8569790	BENT	BOTTOM
MSKU3933746	BENT	BOTTOM
MSKU3933746	DIRTY	LEFT
MSKU4718650	BENT	RIGHT
CAAU6374178	DENT	LEFT
MSKU6374929	DENT	LEFT
MRSU3524590	DENT	RIGHT
TEMU5472643	DENT	LEFT
CAIU7560930	BENT	LEFT
CAIU7560930	BENT	RIGHT
MRKU2700305	BENT	LEFT
MRKU8042897	BENT	BOTTOM
MSKU4307285	DENT	LEFT
SUDU6218827	SCRATCHED	RIGHT
MRKU2367771	BENT	RIGHT
MRKU2367771	BENT	LEFT
MSKU6551011	BENT	RIGHT
GCXU1001663	CUT	TARPAULIN
PONU0055565	TORN	DOORSYSTEM

Without any liability accepted  
 Constanta Sea Container Terminal  
 Planning Department

Signed for receipt only,  
 without prejudice of liability,  
 Discharged same condition as  
 loaded.

Page 7 of 8

M/V "AS NINA"  
 IMO 9401178

Container	Damage type	Damage location
MSKU5143519	BENT	RIGHT
MSKU5143519	TORN	DOORSYSTEM
MRKU2199615	BENT	LEFT
TCNU6304412	DENT	LEFT

Without any liability accepted  
Constanta Sea Container Terminal  
Planning Department

M/V "AS NINA" IMO 9401178  
Received for receipt only,  
without prejudice of liability.  
Loaded.