

DAMAGE REPORT

Inbound carrier: AS NINA

ASNI401S 401S

06-Jan-2024 11:30

Container	Damage type	Damage location
PONU0004104	DENT	CORNER
PONU0004104	CUT	CORNER
MRKU9705504	DENT	BOTTOM
TRHU6303003	DENT	LEFT
TRHU8173207	DENT	LEFT
MRKU6082231	DENT	LEFT
MRKU0825601	DENT	LEFT
PONU0575340	DENT	RIGHT
TRHU1160086	DENT	CORNER
MSKU3139628	DENT	RIGHT
MSKU3139628	DENT	LEFT
HASU4895791	BENT	RIGHT
PONU0615090	DENT	LEFT
MRKU9246030	DENT	LEFT
MRKU9246030	DENT	RIGHT
MSKU7695651	DENT	FRONT
MRSU0252400	DENT	CORNER
TCLU2706519	IMO LABEL	FRONT
TCLU2706519	IMO LABEL	LEFT
TCLU2706519	IMO LABEL	RIGHT
TCLU2706519	IMO LABEL	BACK
MRKU8635260	DENT	DOORSYSTEM
MRSU6284960	DENT	RIGHT
MSKU0888730	DENT	RIGHT
GCXU5529725	DENT	RIGHT
MRKU9801010	DENT	FRONT
MRKU9801010	CUT	FRONT
MRKU9801010	BENT	CORNERPOST

Signed for receipt only,
without acceptance of liability.
Discharged same condition as
loaded. IMO 9401178

Without liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU6630079	BENT	CORNER
MRKU9948989	BENT	RIGHT
MRKU8257982	BENT	RIGHT
MRKU7963330	DENT	RIGHT

Without any liability accepted
Completed South Container Terminal
Planning Department

Signed for receipt only,
with ^{AS} ~~no~~ liability.
Discharge same condition as
loaded.
IMC
9401178