

DAMAGE REPORT

Inbound carrier: AS NINA

ASNI417S 417S

07-May-2024 17:53

Container	Damage type	Damage location
MSKU5244345	DENT	RIGHT
MAEU4684450	HOLE	TARPAULIN
MRKU4076327	DENT	LEFT
MSKU1906227	DENT	CORNER
MRSU5364758	DENT	FRONT
PONU2022046	DENT	LEFT
MRKU9412487	TORN	CORNERPOST
MRKU4941913	DENT	LEFT
PONU7822020	DENT	TOPROOF
PONU7822020	DENT	RIGHT
PONU7822020	DENT	LEFT
MSKU9575320	DENT	RIGHT
MSKU9487575	DENT	RIGHT
GCXU5693322	DENT	RIGHT
MRSU3684393	DENT	RIGHT
TEMU7079152	DENT	LEFT
MSKU1080480	DENT	FLOOR
MSKU1379785	BENT	RIGHT
MSKU1379785	DENT	LEFT
HASU4033077	BENT	LEFT
HASU4033077	DENT	FLOOR
SEKU4449020	DENT	LEFT
SEKU4449020	DENT	RIGHT
MRSU4584640	DENT	LEFT
CAAU6675211	BENT	RIGHT
CAAU6675211	DENT	LEFT
TGHU4788958	DENT	RIGHT
TGHU4788958	DENT	CORNER



*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department
Page 1 of 6

Container	Damage type	Damage location
HASU4568675	DENT	RIGHT
HASU4568675	DENT	LEFT
SEKU4626953	DENT	LEFT
SEKU4626953	DENT	RIGHT
HASU4924708	DENT	RIGHT
HASU4924708	DENT	LEFT
TCKU6964875	BENT	LEFT
PONU7918713	DENT	CORNERPOST
MNBU0371319	BENT	RIGHT
MRKU5758804	TORN	DOORSYSTEM
MRKU4080878	DENT	LEFT
MSKU1506299	BENT	LEFT
MAEU4686555	CUT	TARPAULIN
SUDU8797760	DENT	LEFT
MRSU5099952	DENT	RIGHT
MRKU9290115	BENT	RIGHT
MRKU9290115	BENT	LEFT
TCLU2274293	DENT	RIGHT
MRKU3128658	DENT	LEFT
MRKU8382156	DENT	RIGHT
CIPU5000649	BENT	RIGHT
MRKU7496600	DENT	LEFT
MRKU5032051	CUT	FRONT
HASU5055804	BENT	LEFT
HASU5055804	BENT	RIGHT
SUDU1787991	DENT	RIGHT
MSKU1197590	BENT	LEFT
MSKU1959778	DENT	FLOOR
HASU4558893	DENT	LEFT
BSIU2049558	TORN	CORNERPOST
MRKU9317514	DENT	LEFT
MRKU8220983	TORN	CORNERPOST
MRKU2785719	BENT	LEFT
CRSU1000336	DENT	RIGHT

*Signed for receipt on 09/01/178
without prejudice of liability.
Discharged same condition as
loaded.*



Without any liability accepted
Consentia South Container Terminal
Planning Department
Page 2 of 6

Container	Damage type	Damage location
CAAU6622530	DENT	RIGHT
CAAU6622530	DENT	LEFT
MRKU4509284	DENT	RIGHT
MRKU2465783	BENT	RIGHT
MRKU2465783	BENT	LEFT
MRKU2465783	DENT	CORNER
MNBU3831399	DENT	CORNERPOST
PONU7997878	DENT	RIGHT
HASU4789254	IMO LABEL	FRONT
HASU4789254	IMO LABEL	RIGHT
HASU4789254	IMO LABEL	BACK
HASU4789254	IMO LABEL	LEFT
MRSU5627520	SCRATCHED	LEFT
MNBU3135512	DENT	CORNERPOST
MRKU5510844	IMO LABEL	BACK
SEKU4723790	BENT	LEFT
MRSU4200261	IMO LABEL	FRONT
MRSU4200261	IMO LABEL	RIGHT
MRSU4200261	IMO LABEL	BACK
MRSU4200261	IMO LABEL	LEFT
TEMU6804059	BENT	LEFT
MSKU9743893	BENT	LEFT
TCLU5862120	DENT	LEFT
MRKU5648690	DENT	LEFT
MSKU9305480	DENT	LEFT
SUDU1930510	BENT	CORNERPOST
MRSU4723220	DENT	LEFT
TCNU2872991	BENT	LEFT
MRKU7658321	BENT	LEFT
MIEU3077669	BENT	LEFT
TGBU6805899	DENT	LEFT
TCNU2511746	DENT	LEFT
MRKU8601697	DENT	RIGHT
TCKU1648935	BENT	LEFT

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*



Without any liability accepted
Constanza South Terminal
Planning Department
Page 3 of 6

Container	Damage type	Damage location
MRKU5805594	DENT	LEFT
MRSU5704668	BENT	LEFT
MRSU3384631	DENT	RIGHT
MNBU0247777	DENT	CORNERPOST
MRKU0009974	BENT	LEFT
MRKU0009974	DENT	LEFT
MSKU5106304	DENT	CORNERPOST
MRSU6198163	BENT	BACK
MRSU3033447	BENT	RIGHT
MRKU4000419	BENT	FRONT
MRKU9970848	DENT	RIGHT
SUDU7791200	BENT	BOTTOM
MAEU4665568	HOLE	TARPAULIN
SUDU2841227	HOLE	TARPAULIN
MMAU1103775	CUT	FRONT
MRKU5444491	DENT	LEFT
SUDU5918180	DENT	FLOOR
MSKU8617822	DENT	LEFT
HASU4072793	BENT	RIGHT
HASU4072793	DENT	LEFT
MRKU5570695	DENT	RIGHT
MSKU4230120	CUT	FLOOR
MRSU3286738	DENT	RIGHT
MRKU4466557	DENT	RIGHT
SUDU6960991	DENT	LEFT
MSKU9078622	DENT	RIGHT
MRKU8718317	BENT	RIGHT
MAEU4132002	CUT	TOPROOF
CAAU5426180	DENT	RIGHT
MRKU5726598	TORN	DOORSYSTEM
MRKU2613670	DENT	RIGHT
MSKU1719735	DENT	RIGHT
MRKU2902543	DENT	LEFT
SUDU6584683	DENT	RIGHT

*Signed for receipt only
without prejudice of liability.
Discharged same condition as
loaded.*



*Without any liability accepted
Constanta South Container Terminal
Planning Department*

Container	Damage type	Damage location
SUDU6584683	DENT	CORNER
MRKU5947290	DENT	LEFT
MIEU0008495	DENT	FRONT
HASU4273798	DENT	LEFT
MSKU4340088	BENT	BOTTOM
TCKU7578136	DENT	LEFT
TCKU7120708	DENT	RIGHT
MRKU4673873	BENT	LEFT
AMFU3190248	DENT	CORNER
MRKU0285020	DENT	LEFT
TCLU6363167	DENT	RIGHT
MSKU5111086	BENT	RIGHT
MSKU5111086	BENT	LEFT
MRKU2637563	DENT	LEFT
MSKU8223325	DENT	LEFT
TCNU2053962	BENT	RIGHT
TCNU2053962	BENT	LEFT
MSKU1521170	BENT	RIGHT
MSKU1521170	DENT	CORNER
SUDU7439566	DENT	LEFT
SUDU6749377	BENT	LEFT
TCKU7078125	DENT	FLOOR
CAIU8051670	DENT	LEFT
MRSU4449402	DENT	RIGHT
MRSU4449402	DENT	LEFT
MRSU6469012	DENT	RIGHT
MSKU5403088	BENT	BOTTOM
MRKU4319622	DENT	RIGHT
DAYU6128091	DENT	RIGHT
DAYU6128091	DENT	CORNERPOST
MRKU4596334	DENT	RIGHT
MRKU4596334	BENT	LEFT
MRKU4596334	DENT	LEFT
MSKU0687741	BENT	RIGHT



Signed for receipt only,
 without prejudice of liability.
 Discharged same condition as
 loaded.

Without any liability accepted
 Constanta South Container Terminal
 Planning Department
 Page 5 of 6

Container	Damage type	Damage location
GESU5869619	DENT	LEFT
GESU5869619	BENT	LEFT
MRKU0146581	BENT	RIGHT
MRKU4919289	DENT	LEFT
MMAU1200179	CUT	FRONT
SUDU5755354	DENT	LEFT
HASU4713304	DENT	LEFT
TRLU8044126	BENT	RIGHT
MRKU0292272	DENT	RIGHT
MRKU0292272	BENT	LEFT
MRKU0292272	DENT	LEFT
SUDU8902530	DENT	FRONT
MSKU0619602	BENT	LEFT
MRSU3413489	BENT	RIGHT
MSKU1445640	BENT	FRONT
MSKU0522612	HOLE	TOPROOF
MSKU6561447	DENT	CORNERPOST
MRKU0478890	DENT	LEFT
PONU7157229	DENT	LEFT
MRKU5502279	DENT	LEFT
MRKU3691933	DENT	RIGHT
MRKU3691933	DENT	LEFT
MRKU3762997	BENT	RIGHT
SUDU8999837	BENT	FRONT
TCNU1129298	BENT	LEFT
MSKU7814107	DENT	CORNER

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*



Without any liability accepted
Constanta South Container Terminal
Planning Department
Page 6 of 6