

DAMAGE REPORT

Inbound carrier: MAX SCHULTE

MASH531S 531S

30-Jul-2025 22:17

Container	Damage type	Damage location
SUDU8995934	DENT	LEFT
TCKU6782720	DENT	RIGHT
MSKU4630575	DENT	LEFT
HASU4221433	BENT	TOPROOF
HASU4221433	BENT	RIGHT
HASU4221433	SCRATCHED	LEFT
MRKU3913060	BENT	LEFT
TGBU6639822	DENT	RIGHT
FANU1737581	BENT	LEFT
HAMU1297048	DENT	RIGHT
FANU1211112	BENT	LEFT
BMOU5828181	SCRATCHED	LEFT
MRSU5598490	DENT	LEFT
BMOU6661490	DENT	LEFT
GCXU5699974	DENT	LEFT
MRSU3706390	DENT	RIGHT
MRSU3706390	HOLE	TOPROOF
MRKU3106561	DENT	LEFT
MRSU5397767	BENT	RIGHT
MRSU5397767	BENT	LEFT
HASU4231895	IMO LABEL	FRONT
HASU4231895	IMO LABEL	RIGHT
HASU4231895	IMO LABEL	DOOR
HASU4231895	DENT	LEFT
HLBU1941280	BENT	LEFT
TEMU1597257	DENT	RIGHT
TCKU6784805	IMO LABEL	FRONT
TCKU6784805	IMO LABEL	DOOR

Discharged as loaded

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
TCKU6784805	IMO LABEL	RIGHT
TCKU6784805	IMO LABEL	LEFT
MRSU4462364	DENT	LEFT
MRKU4347223	DENT	RIGHT
TLLU5964520	DENT	LEFT
DAYU2165733	DENT	CORNERPOST
BEAU5109054	DENT	CORNER
CAAU7181044	DENT	LEFT
MSKU1501574	DENT	LEFT
HLBU2403838	DENT	LEFT
MRSU5420321	DENT	LEFT
MRKU6443381	DENT	DOORSYSTEM
HAMU1058552	DENT	RIGHT
TCLU3266440	BENT	LEFT
UACU5449244	DENT	RIGHT
GESU1070630	BENT	FLOOR
SUDU2850996	CUT	TARPAULIN
GATU8528462	DENT	LEFT
TRHU6230458	HOLE	TOPROOF
TRHU6230458	HOLE	TOPROOF
HLBU3202458	BENT	LEFT
MMAU1355490	DENT	LEFT
FTAU1563903	DENT	RIGHT
SUDU6173656	DIRTY	FRONT
CAIU8310853	DENT	RIGHT
HLBU2452895	DENT	RIGHT
CAAU5411744	DENT	RIGHT
TGHU9887280	DENT	LEFT
TGHU9887280	DENT	RIGHT
HASU5205695	DENT	RIGHT
TRHU5299017	DENT	LEFT
HLXU8246878	BENT	FRONT
FANU1916695	DENT	RIGHT
FANU1916695	DENT	LEFT

Discharged

Without any liability accepted
Constans South Container Terminal
Planning Department

Container	Damage type	Damage location
MNBU0016715	DENT	LEFT
MNBU0016715	DENT	RIGHT
FANU1807776	DENT	RIGHT
FANU1807776	DENT	LEFT
SEGU1597060	BENT	LEFT
GESU5806890	DENT	RIGHT
MRKU3936661	DENT	RIGHT
MSKU8893775	SCRATCHED	LEFT
CAAU7598911	CUT	FRONT
TCNU1514761	DENT	LEFT
SUDU6929949	DENT	LEFT
SUDU6929949	BENT	RIGHT
MRSU6151079	DENT	LEFT
MRKU8984873	DENT	FRONT
HLBU2687713	DENT	RIGHT
MSKU8952456	RUSTED	FRONT
MSKU8952456	RUSTED	LEFT
MSKU8952456	RUSTED	RIGHT
MNBU3254960	CUT	FRONT
MNBU3053733	DENT	LEFT
MNBU3053733	DENT	RIGHT
TCKU7762360	DENT	RIGHT
TGHU1686016	DENT	LEFT
MSKU1573949	IMO LABEL	FRONT
MSKU1573949	IMO LABEL	DOOR
MSKU1573949	IMO LABEL	LEFT
MSKU1573949	IMO LABEL	RIGHT
TCLU6682760	DENT	LEFT
MRKU4925189	DENT	LEFT
MAEU4095742	CUT	TARPAULIN
MRKU6364831	DENT	LEFT
MRKU6364831	DENT	RIGHT
HASU1125694	BENT	RIGHT
TGBU3755475	IMO LABEL	DOORSYSTEM

Discharged / As loaded

Without any liability accepted
Constanza South Container Terminal
Planning Department

Container	Damage type	Damage location
MRSU6566521	DENT	RIGHT
MAEU4182493	CUT	TARPAULIN
UACU8343641	BENT	LEFT
MRKU0000806	BENT	RIGHT
CAAU7597031	BENT	RIGHT
MRKU1018918	DENT	RIGHT
MRKU6157794	DENT	LEFT
TCNU3527367	RUSTED	LEFT
TCNU3527367	RUSTED	RIGHT
FANU1480955	BENT	LEFT
FANU1480955	BENT	RIGHT
MSKU1635655	CUT	FRONT
TCKU6803269	BENT	RIGHT
TCKU6803269	IMO LABEL	RIGHT
TCKU6803269	IMO LABEL	DOOR
TCKU6803269	IMO LABEL	FRONT
TCKU6803269	BENT	LEFT
MSKU9108429	DENT	LEFT
HLXU8448098	DENT	LEFT
MNBU0204646	CUT	RIGHT
SUDU6253392	DENT	LEFT
FANU1025118	DENT	LEFT
UETU5479599	DENT	LEFT
MAEU4677640	CUT	TARPAULIN
MRSU5043676	BENT	LEFT
HAMU1324550	DENT	RIGHT
CAIU9776548	DENT	DOORSYSTEM
UETU2735980	BENT	LEFT
MSKU4128588	BENT	LEFT
MSKU4128588	BENT	RIGHT
TCKU6075538	DENT	LEFT
HASU4263629	IMO LABEL	FRONT
HASU4263629	IMO LABEL	RIGHT
HASU4263629	IMO LABEL	DOOR

Discharged as loaded



Without any liability accepted
Consist's South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU0719284	BENT	LEFT
HLBU1955410	DENT	FRONT
HLBU1955410	CUT	FRONT
MRSU3073120	DENT	RIGHT
MSKU4154761	BENT	RIGHT
MRSU3435169	DENT	RIGHT
PONU8189067	DENT	RIGHT
MRSU6019904	IMO LABEL	RIGHT
MRSU6019904	IMO LABEL	LEFT
MRSU6019904	IMO LABEL	DOOR
MNBU3170719	BENT	LEFT
MNBU3170719	BENT	RIGHT
HLXU8554607	DENT	LEFT
MAEU9189124	DENT	RIGHT
TLLU5825314	SCRATCHED	LEFT
MRKU6232455	BENT	LEFT
HLBU8034716	BENT	FRONT
MRSU5309637	BENT	LEFT
HAMU1219765	DENT	RIGHT
MSKU0981822	DENT	RIGHT
FANU3757648	DENT	LEFT
MRSU5472177	BENT	LEFT
MRSU5472177	BENT	RIGHT
TRLU8046392	DENT	LEFT
MRKU4026244	DENT	LEFT
HLBU2713962	DENT	LEFT
TRHU5249628	SCRATCHED	LEFT
MSKU0727485	BENT	RIGHT
MRKU2365824	RUSTED	CORNERPOST
SUDU6704053	IMO LABEL	FRONT
SUDU6704053	IMO LABEL	RIGHT
SUDU6704053	IMO LABEL	DOOR
MRKU5964791	IMO LABEL	FRONT
MRKU5964791	IMO LABEL	RIGHT

Without any liability accepted
 Constantia South Container Terminal
 Planning Department

Discharged as loaded
 OFFICER

Container	Damage type	Damage location
MRKU5964791	IMO LABEL	DOOR
MRKU2684776	DENT	RIGHT
MRKU2684776	BENT	RIGHT
TRHU6921948	IMO LABEL	FRONT
TRHU6921948	IMO LABEL	RIGHT
TRHU6921948	IMO LABEL	DOOR
TRHU6921948	IMO LABEL	LEFT
TCNU5011317	IMO LABEL	FRONT
TCNU5011317	IMO LABEL	DOOR
TCNU5011317	IMO LABEL	RIGHT
TCNU2978200	RUSTED	RIGHT
TCNU2732222	DENT	LEFT
HASU4370550	BENT	LEFT
MRSU5195663	DENT	LEFT
MRKU6025669	DENT	LEFT
MRSU3729760	BENT	LEFT
MAEU4136625	CUT	TARPAULIN
GCXU5798961	DENT	LEFT
MAEU4074360	CUT	TARPAULIN
HLBU1623268	DENT	LEFT
DFSU2694075	DENT	LEFT
DFSU2694075	DENT	RIGHT
FFAU2210122	BENT	RIGHT
MTSU9665162	BENT	LEFT
HLBU2254740	DENT	LEFT
MRKU5446180	BULGED	RIGHT
MRKU5446180	BULGED	LEFT
SUDU8707180	DENT	LEFT
UACU5461770	CUT	LEFT
HLBU3155736	DENT	LEFT
TCNU8147312	DENT	LEFT
HAMU3028639	HOLE	TOPROOF
NIDU5201863	BENT	CORNERPOST
HLBU2253738	BENT	LEFT

Discharged as loaded



Without any liability
Consian's Port Container Terminals
Planning Department

Container	Damage type	Damage location
TGCU2090595	BENT	LEFT
TCNU4234044	BENT	RIGHT
TCNU4234044	BENT	DOORSYSTEM
UETU5823425	DENT	LEFT
MRSU5038561	DENT	RIGHT
MRKU5172670	DENT	RIGHT
MRKU3564184	DENT	LEFT
MSKU4118131	DENT	RIGHT
MRKU8661525	DENT	RIGHT
SKIU9114130	DENT	RIGHT
CAAU5946134	DENT	LEFT
TCLU3016117	DENT	RIGHT
SUDU8592749	DENT	FRONT
TGHU6727653	DENT	LEFT
PONU8114406	DENT	RIGHT
MSKU1378768	BENT	LEFT
MRSU4374495	BENT	RIGHT
HLXU1136328	DENT	LEFT
SEKU6932206	DENT	FRONT
SEKU6932206	HOLE	FLOOR
HAMU1948181	IMO LABEL	LEFT
MRKU3803205	RUSTED	DOOR
GCXU5732347	SCRATCHED	LEFT
SEKU6899900	BENT	FRONT
MRKU4030922	BULGED	RIGHT
MSKU1992652	DENT	LEFT
MRKU6058765	DENT	LEFT
MRKU4431000	BENT	RIGHT
MRKU4431000	DENT	LEFT
GCXU5554841	CUT	CORNER
MRKU5416144	DENT	RIGHT
DFSU1267510	BENT	LEFT
DFSU1267510	DENT	RIGHT
MRSU5863628	CUT	TOPROOF

Without any liability accepted
Constan's South Container Terminal
Planning Department

Discharged as loaded
OFFICER
SINGAPORE

Container	Damage type	Damage location
TEMU4486489	BENT	LEFT
TEMU4486489	BENT	RIGHT
SUDU6561800	DENT	RIGHT
HLBU8063587	CUT	TARPAULIN
TCNU1472809	BENT	FRONT
FFAU4772514	DENT	LEFT
MSKU9563398	DENT	LEFT
MRKU5195660	DENT	RIGHT
MRKU0461794	DENT	RIGHT
HLBU1317735	BENT	RIGHT
MSKU8536248	DENT	RIGHT
MNBU3707351	DENT	CORNERPOST
MNBU3707351	CUT	FRONT
MSKU0242041	BENT	LEFT
MNBU3231938	DENT	LEFT
MNBU3231938	DENT	RIGHT
MRKU2577382	DENT	FLOOR
UACU5860682	DENT	RIGHT
BEAU4462072	DENT	LEFT

Without any liability accepted
Constanza South Container Terminal
Planning Department

Discharged

